

Sample Required Responses

- 003 ***NOT COMPLETE***- None or some of the facilities have been marked, more time needed, coordination or assistance required to complete locating of facility
Sample 003: Contacted John Miller at ABC electric company on Monday, May 3 at 10:00am Mary Smith at Smith Locators 248-555-5555. Unable to locate lines. Need additional assistance from Consumers Energy.
- 005 ***ON GOING COORDINATION***- On-going mutual co-operation between facility owner operator and excavator
Sample 005: Contacted Barry Brown from Build a Highway Company on Monday, May 3 at 10:00am. Mary Smith at Smith Locators 248-555-5555. Large project that requires multiple days of location. Daily communication with Barry to continue marking highway.
- 006 ***NOT MARKED***-NO ACCESS TO WORK AREA-Facility owner operator could not get access to work area, and requires coordination with excavator
Sample 006: Contacted Jack Brown on Monday, May 3 at 10:00am. Mary Smith at Smith Locators 248-555-5555. Gate locked. Unable to access property. Jack Brown out of town. Need to reschedule.
- 009 ***ADDITIONAL LOCATING REQUIRED***- Facility owner discovered field conditions require additional locating and will communicate with excavator on resolution of additional locating issues
Sample 009: Contacted Jill White homeowner on Monday, May 3 at 10:00am. Mary Smith at Smith Locators 248-555-5555. Hazardous conditions on property due to severe weather. Return to site when conditions change.
- 011 ***NOT MARKED***-EXCAVATOR CONTACTED FOR ADDITIONAL INFORMATION- Facility owner operator reached out to the excavator as noted on the locate request and requires additional information to properly complete locate request. Excavator required to contact facility owner/operator.
Sample 011: Left message for Bill Murphy on Monday, May 3 at 10:00am. Mary Smith at Smith Locators 248-555-5555. Description of property does not match ticket. Waiting for return call.

GREEN- Dig with caution following PA174 requirements

YELLOW- Contact facility owner operator; then dig with caution following PA174 requirements

RED- Do not Dig

* Providing a **URL** or completing the **Comments** field is required.