

MISS DIG Positive Responses as adopted by TIME and MDPB committees.

Positive Responses for Standard Dig Notice Tickets effective 3/1/2015

- 000 **RESPONSE PENDING**- System generated default response attached to initial request
- 001 **NO CONFLICT**- Facility is outside of stated area/scope of excavation
- 002 **MARKED**- Facilities have been marked
- 003 **NOT COMPLETE**- None or some of the facilities have been marked, more time needed, coordination or assistance required to complete locating of facility
- 004 **MARKED-UTILITY REQUIRED ON SITE DURING EXCAVATION**- Facility owner operator required to be on site when excavating within noted scope of work for this specific facility
- 005 **ON GOING COORDINATION**- On-going mutual cooperation between facility owner operator and excavator
- 006 **NOT MARKED-NO ACCESS TO WORK AREA**-Facility owner operator could not get access to work area, and requires coordination with excavator
- 007 **STATED SCOPE OF WORK COMPLETE**- Facility owner operator confirmed stated scope of work completed
- 008 **FACILITY RESPONSE NOT REQUIRED**- This response is specifically for locate requests intended for a specific facility or facilities that have NOT been requested to locate by the excavator. Example- Locate Gas and Electric only, all other facility owners (water, sewer, telephone, cable TV, etc.) would respond "**FACILITY RESPONSE NOT REQUIRED**"- Facilities requested to be located would choose from the other possible positive responses
- 009 **ADDITIONAL LOCATING REQUIRED**- Facility owner discovered field conditions require additional locating and will communicate with excavator on resolution of additional locating issues
- 013 **CANCELED**- System generated response indicating the dig notice was canceled

- 999 **HAS NOT RESPONDED**- System generated response indicating the facility owner operator has not responded to the request

GREEN- Dig with caution following PA174 requirements

YELLOW- Contact facility owner operator, Dig with caution following PA174 requirements

RED- Do not Dig

Positive Responses for Design Ticket Requests are not color coded as they are not Dig Notices

- 201 DESIGN-NO FACILITIES- *No Facilities in area as described in the scope of excavation*
- 202 DESIGN-TASK COMPLETED- *Facility owner operator sent record drawings to designer*
- 203 DESIGN-MARKING REQUIRED- *As defined in Public Act 174 Section 6a paragraph (3)*

(3) The response to a design ticket is to provide general information regarding the location of underground facilities, not to mark any facilities. However, if a facility owner or operator does not have drawings or records that show the location of a facility, the facility owner or operator shall mark that facility under the procedures described in section 7. A design ticket or information provided in response to a design ticket does not satisfy the requirement under this act for excavation or blasting notice to the notification system or marking the approximate location of facilities for blasting or excavation.

Positive Response document date 12/2/2014